




رسالة سلامة
Safety Communication

To: Healthcare Provider

إلى: مقدمي الرعاية الصحية

Title	Two issues related to ParaPAC plus™ Model 300 and Model 310 Ventilator	العنوان
Medical Device Description	Ventilator	اسم ووصف الجهاز/المستلزم الطبي
Manufacturer	Smiths Medical	اسم المصنع
Authorized Representative	N/A	الممثل المعتمد
Medical Devices Marketing Authorization (MDMA)	GHTF-2017-2479	إذن التسويق
Potential /Associated risks	<ul style="list-style-type: none">There is potential for inadvertent tidal volume knob movement from the original setting, when set at high (1000 – 1500 mL) and low (70 – 150 mL) settings.There is potential for the patient outlet connector to loosen/detach from the paraPAC Plus™ P300 and P310 ventilators impacting the active ventilation function.	المخاطر المحتملة/ المرتبطة بالجهاز أو المستلزم الطبي
Recommendations	<p>General Recommendations for Healthcare Providers and Users</p> <ul style="list-style-type: none">Please stop use the affected devices.If you have any of the affected devices please contact NCMDR by NCMDR.MD@sfd.gov.sa	التوصيات
For Reporting	  	للإبلاغ