

Safety Communication

رسالة سلامة

May Have Cybersecurity Vulnerabilities

Device/ Product Description:	Ventilators, Hamilton-T1	
Manufacturer:	HAMILTON MEDICAL AG	
Problem Summary:	<p>Vulnerabilities:</p> <ul style="list-style-type: none"> - use of hard-coded credentials cwe-798 - missing xml validation cwe-112 - exposure of sensitive information to an unauthorized actor cwe-200 <p>RISK EVALUATION: Successful exploitation of these vulnerabilities could allow attackers with physical access to the device to obtain sensitive information or crash the device being accessed.</p> <p>For more information, please check Here.</p> <p>If you think you had a problem with your device or a device your patient uses, please report the problem to SFDA through: NCMDR Vigilance system 19999 unified call center</p>	
	AR name:	daleel alraeda trading est
	Assigned Contact Person:	Malek AlTurayri
	Mobile/Phone:	+(966) 550270075
	Email:	malekaltrairi@gmail.com