

Safety Communication

رسالة سلامة

Infection – Late delivery of Blood Solution

Device/ Product Description:	Volumed Transfusion Set, Non-Vented, DEHP-Free PVC, 235cm, Robson Clamp and Male Luer Lock. Sterile Item for Single Use	
Device Model:	Volumed® Set	
Affected products:	Catalogue:	APTPK0J
	Batch:	19PH427
Manufacturer:	Phoenix s.r.l	
Problem:	Disconnection between drip chamber and tubing which may cause Possible Infection and/or late delivery of blood solution.	
Recommendation /Actions:	<ul style="list-style-type: none"> • Make sure that this document is reached to the end-users. • Identify and quarantine any affected products • Contact the authorized representative for the required support. <p>For more information please click here.</p> <p>If you think you had a problem with your device or a device your patient uses, please report the problem to SFDA through: NCMDR Vigilance system (19999) unified call center</p>	

Authorized Representative Details	AR name:	Salem Abdulraheem Bawazeer Est for Trading 
	Assigned Contact Person:	Salem Bawazeer
	Mobile/Phone:	+(966) 505504255
	Email:	b_salem10@hotmail.com

